

Version number:	V1
Date adopted by the Local Governing	Local Governing Body
Body (LGB):	November 2022
Scheduled review date:	Autumn 2025
Statutory or Best Practice policy:	Best Practice
Appendices:	No
School or Trust policy:	School

St Agnes Academy Accessibility Plan 2022-2024

The Disability Access Plan addresses and recognises the requirements of the Equality Act 2010 (Disability Discrimination Act (DDA) 1995 AND 2005). The plan identifies work required in order to give all disabled users access to all parts of the building and includes recommendations for required remedial actions, ongoing monitoring and control measures that illustrate good practice in terms of meeting the needs of disabled people.

Purpose of Plan

The purpose of this plan is to show how St Agnes Academy intends, over time, to increase the accessibility of our school. We will continue to improve all aspects of the physical environment of the school site, the curriculum and written information so that all students with a disability can take full advantage of the education and associated opportunities provided by St Agnes Academy.

Definition of disability

A person has a disability if he or she has a physical or mental impairment that has a substantial and long-term adverse effect on his or her ability to carry out normal day-to-day activities.

Key Objective

To reduce and eliminate barriers for access to the curriculum and to full participation in the school community for pupils, and prospective pupils, with a disability.

Principles

- Compliance with the DDA is consistent with our school's aims and equal opportunities policy and SEND and Inclusion policies
- The school recognises its duty under the DDA:
 - Not to discriminate against disabled pupils in their admissions and exclusions, and provision of education and associated services
 - Not to treat disabled pupils less favourably
 - To take reasonable steps to avoid putting disabled pupils at a substantial disadvantage
 - To publish an accessibility plan
- In performing their duties, governors and staff will have regard to the DRC Code of Practice.
- The schools recognises and values parents' knowledge of their child's disability and its effect on his/her ability to carry out normal activities, and respects the parents' and child's right to confidentiality
- The school provides all pupils with a broad and balanced curriculum, differentiated and adjusted to meet
 the needs of individual pupils and their preferred learning styles; and endorses the key principles in the
 National Curriculum Framework, which underpin the development of a more inclusive curriculum
 - Setting suitable learning challenges
 - Responding to pupils' diverse learning needs
 - Overcoming potential barriers to learning and assessment for individuals and groups of pupils

Increasing Access for disabled pupils to the school curriculum

This includes teaching and learning and the wider curriculum of the school such as participation in after school clubs, leisure and cultural activities or school visits.

Improving teaching and learning lies at the heart of our school. Through self-review and continuous professional development, we aim to enhance staff knowledge, skills and understanding to promote excellent teaching and learning for all children. We aim to meet every child's needs within mixed ability, inclusive classes.

It is a core value of our school that all children are enabled to participate fully in the broader life of the school. Consequently, all children have always been permitted to attend age relevant after school clubs, leisure and cultural activities or school visits. The only exception would occur if a child had breached school rules e.g. through aggressive behaviour at a club, when deprivation of club attendance may be used as a suitable short-term sanction and to ensure the safety of other children.

Improving access to the physical environment of the school

This includes improvements to the physical environment of the school and physical aids to access education.

We have a made appropriate changes to the building to meet the needs of the pupils. Provision, in exceptional cases, will be negotiated when the child's specific needs are known.

We have a wide range of equipment and resources suitable for the day-to-day use of children in the age range. The school improvement plan process will consider such needs on an annual basis.

Improving the delivery of written information to disabled pupils

This will include planning to make written information that is normally provided by the school to its pupils available to disabled pupils. Examples might include handouts, timetables, textbooks and information about school events. The information should take account of pupils' disabilities and pupils' and parents preferred formats and be made available within a reasonable time frame.

In planning to make written information available to disabled pupils, we again need to establish the level of current need and be able to respond swiftly to changes in the range of need. For example, it would be a misuse of finite school resources to commit funding to providing Braille or large print versions of all school materials (identified in italics above) if there are no children on roll who require such access. However, the school will identify agencies and sources of such materials to be able to make provision whenever it is required.

Teachers will always need to be sensitive to presenting materials to children in appropriate formats eg reading aloud, overhead projections, should that be necessary. This is a core part of a teacher's work.

Financial Planning and control

The headteacher, SLT and the governors will review the financial implications of the accessibility plan as part of the normal budget review process.

St Agnes Academy

St Agnes Academy is a co-educational school with approximately 358 children on roll whose ages range from 4 -11 years.

The original school building was built in 1988 with a secondary, extension building constructed in 2017. Across the two buildings the school has fourteen classrooms, each with their own cloakroom area. There is a large hall that is used for PE, assemblies and lunch time. The library is well stocked with lots of books for children to choose from which the children may choose to read. The Key Stage 2 building is built over two floors. There is a lift and two separate sets of stairs. The stairs have handrails on both sides with safety glass balustrades for increased light and visibility. The new building has a large disabled toilet complete with shower, electric hoists and changing facilities.

Outside there are two adventure play areas (KS1 and 2), two tarmac playgrounds, a covered and enclosed EYFS outdoor learning area and a forest school area. The large field is used on dry days for playtime and for games lessons. The grounds are well laid out and comprise various raised beds for the children's gardening club. All outdoor areas are accessible, with an alternative ramp/slope being provided where there are steps and gated areas being wide enough for wheelchair users.

APPENDIX A - 1 of 9

Access Check List for St Agnes Academy – January 2022 Approach and Car Parking

Consider each question from the perspective of each type of disability:

	Question	Υ	N	Action Point
1	Is the building within convenient distance of a public highway?	\checkmark		
2	Is the building within convenient distance of public transport?	\checkmark		
3	Is the building within convenient distance of car parking?	\checkmark		
4	Is the route clearly marked/found?	✓		
5	Is the route free of kerbs?	✓		
6	Is the surface smooth and slip resistant?	✓		
7	Is the route wide enough?	✓		
8	Is it free of such hazards as bollards, litter bins, outward opening windows and doors or overhanging projections?	✓		
9	Is it adequately lit?	\checkmark		
10	Is it identified by visual, audible and tactile information?	✓		Visual only.
11	Is there car parking for people with reduced mobility?	✓		
12	Is the car parking clearly marked out, signed, easily found and kept free from misuse?	✓		
13	Is the car parking as near the entrance as possible?	\checkmark		
14	Is the car parking suitably surfaced?	\checkmark		
15	Is the route to the building kept free of snow, ice and fallen leaves?	✓		
16	Is the route level? (ie no gradient steeper than 1:20 and no steps)	√		

General Notes for approach and parking:

^{*}Very clear markings painted on car park, indicating walkways, direction of traffic, allocated parking etc * Clear signage of reception area close to the reception – consider additional signage nearer to main car park (next to notice board on preschool fence?)

APPENDIX A - 2 of 9

Access Check List for St Agnes Academy – January 2022 Routes and external level change including ramps and steps

Consider each question from the perspective of each type of disability:

	Question	Υ	N	Action Point
1	Is there a ramp, with level surfaces at top/intermediate/bottom?	✓		Low gradient slopes
2	Is it wide enough and suitably graded?	√		
3	Is the surface slip resistant?	✓		
4	Are there kerbs and are there edges protected to prevent accidents?	✓		
5	Are there handrails to one or both sides?		✓	Not steep enough to require handrail
6	Are there (alternative) steps & ramp	✓		
7	Identified by visual/tactile information?		✓	
8	Are there handrails to one or both sides?	✓		Both sides of both sets of steps
9	Are ramps and steps adequately lit?	✓		
10	Are treads and risers consistent in depth and height?	√		
11	Are all nosings marked and/or readily identifiable?	√		
12	Are landings of adequate size and are they provided at intermediate levels in long flights?	✓		

General Notes for routes and external level change including ramps and steps:

The route to the KS2 play area is sloped. The gradient is not steep enough to require a handrail. There are steps from the staff car park to the KS2 play area. The steps have a handrail on both sides. The route to the lower KS1 play area is sloped. The gradient is not steep enough to require a handrail. There are steps leading from the EYFS enclosed area onto the lower KS1 play areas. The steps have a handrail on both sides. An alternative sloped route is available. Again, the gradient of the slope is not steep enough to require a handrail.

*Consider adding signage at top and bottom of both sets of steps, directing user to alternative slope.

APPENDIX A – 3 of 9

Access Check List for St Agnes Academy – January 2022 <u>Entrances – including Reception</u>

Consider each question from the perspective of each type of disability:

	Question Question	Υ	N	Action Point
1	Is the door clearly distinguishable from the façade?	✓		
2	If glass, is it visible when closed?	✓		
3	Does the clear door opening or one leaf when opened permit passage of a wheelchair or double buggy?	✓		
4	Does it have a level or flush threshold, and a recessed matwell?	✓		Entrance mat sits on top of carpet. Slight raised edge on threshold (1.5cm)
5	Is there visibility through the doorway from both sides at standing and seated levels?	✓		
6	Is there a minimum 300mm wide wheelchair manoeuvre space beside the leading edge of the door to clear door swing?	✓		
7	Can the door furniture be used at both standing and seated height?	✓		
8	Can it be easily grasped and operated?	✓		
9	 If the door has a closer mechanism does it have: Delayed closure action? Slow-action closer? Minimal closure pressure? 	✓		
10	If the door is power-operated does it have visual and tactile information?	✓		
11	If the door is security-protected is the system suitable for use by and within reach of people with sensory or mobility impairments?	✓		
12	If there is a lobby, do the inner and outer doors meet the same criteria?	✓		
13	Do lobby layouts enable all users to clear one door before going through the next?	✓		
14	Are signs designed and positioned to inform those with visual impairments and wheelchair users with reduced eye levels?	✓		
15	Does the lighting installation take account of the needs of visually disabled people?	✓		
16	 Are floor spaces Slip resistant, even when wet? Of a quality that is sympathetic to acoustics – ie not so 'hard' as to cause acoustic confusion? Firm for wheelchair manoeuvre 	✓		

17	Are junctions between floor surfaces arranged in a way that avoids presenting tripping hazards and causing visual confusion?	✓		
18	Is any reception point suitable for approach and use from both sides by people in standing and seated positions?	√		
19	Is it fitted with an induction loop?		✓	
20	For those progressing to other parts of the building is information provided by signs, supported by tactile information such as a map or model?		✓	Maps of school form part of the fire escape information, located at fire exit signs.

General Notes for entrances including reception:

^{*}Consider displaying a whole school map of the school in the foyer

^{*}Consider having signage to head teachers office, disabled toilets etc by the entrance to the school from the foyer

APPENDIX A - 4 of 9

Access Check List for St Agnes Academy- January 2000 Horizontal Movement and Assembly

Consider each question from the perspective of each type of disability:

	Question	Υ	N	Action Point
1	Is each corridor/passageway/aisle wide enough for a wheelchair	✓		
_	user to manoeuvre and for other people to pass?			
2	Is each corridor etc. free from obstruction to wheelchair users	\checkmark		
	and from hazards to people with impaired vision? Do any lobbies allow users (including wheelchair users) to clear			
3		\checkmark		
	one door before approaching the next with minimal manoeuvre			
4	Is turning space available for wheelchair users?	V		
5	Do natural and artificial lighting avoid glare and silhouetting?	✓		
6	Are there visual clues for orientation?	✓		Could be clearer and at a lower level.
	Do floor surfaces:	,		
7	 Allow ease of movement for wheelchair users? 	\checkmark		
	Avoid light reflection and sound reverberation?			
	Are direction or information signs (including means of escape)			Could be
8	visible from both sitting and standing eye levels, and are they in	\checkmark		clearer and at
	upper and lower case, and large enough type to be read by those with impaired vision?			a lower level.
	those with impalied vision:			Some brail
	Are there tactile signs and information for those with impaired			signs around
9	vision?		✓	school but
				inconsistent
10	Is the maintenance of these items checked regularly?	✓		
11	Is lighting designed to meet a wide range of needs?	✓		
12	Is sufficient circulation space allowed for wheelchair users?	✓		
13	Is it maintained clear of obstructions which could create hazards	√		
13	for people with visual disabilities?	*		
14	Are seating arrangements/spaces suitable for use by people	✓		
14	with visual disabilities?	-		
15	Are all areas for assembly/meeting equipped with an induction		✓	
	loop system?			

General Notes for horizontal movement and assembly:

^{*}Use of Braille signs inconsistent across all school – this would be reviewed if the need arose in the future

APPENDIX A - 5 of 9

Access Check List for St Agnes Academy – January 2022 <u>Doors</u>

Consider each question from the perspective of each type of disability:

	Question	Υ	N	Action Point
1	Do the doors serve a functional/safety purpose?	\checkmark		
2	If glass, are they visible when shut?			
3	Can people standing or sitting in a wheelchair see each other, and be seen from either side of the door?	✓		
4	Does the clear opening width permit wheelchair access	\checkmark		
5	On the opening side of the door is there sufficient space (300mm) to allow the door handle to be grasped and the door swung past a wheelchair footplate?	✓		
6	Is any door furniture/handle at a height for standing/sitting use?			
7	Are door/handles clearly distinguished?	\checkmark		
8	Can the door furniture/handles be easily operated/grasped?	✓		
9	If door closers/mechanisms are fitted do they provide the following: • security linkage? • delay-action closure? • Slow-action closure? • Minimum closure pressure?	✓ ✓ ✓		
10	Is door/mechanism function checked regularly?	✓		

General Notes for doors:

• Some exits/ entrances from EYFS and KS1 area are difficult (door release quite high? Limited space for footplate clearance), only one way etc. Alternative exit/entrance is available.

APPENDIX A – 6 of 9

Access Check List for St Agnes Academy– January 2022 <u>Lavatories</u>

Consider each question from the perspective of each type of disability:

	Question	Υ	N	Action Point
1	Is WC provision made for people with disabilities?	\checkmark		
2	Do all lavatory areas have slip-resistant floors?	✓		
3	Are all fittings readily distinguishable from their background?	✓		
4	Are all door fittings/locks easily gripped and operated?	✓		
5	Can ambulant disabled people manoeuvre and raise and lower themselves in standard cubicles?	✓		
6	Is provision made for wheelchair users in disabled toilets?	✓		
7	Is wheelchair approach free of steps/narrow doors/obstructions etc?	✓		
8	Is the location clearly signed?	✓		Signage on doors
9	Is there sufficient space at entry to the compartment for wheelchair manoeuvre and door opening?	✓		
10	Are the door fittings/locks and light switches easily reached and operated?	✓		
11	Is there an emergency call system and is someone designated to respond?	✓		
12	Can the emergency call system be operated from floor level?	✓		
13	Is the wheelchair WC compartment large enough to permit manoeuvre for frontal lateral/angled/backward transfer, with or without assistance?	✓		
14	Are the fittings arranged to facilitate these manoeuvres	√		
15	Are handwashing and drying facilities within reach of someone seated on the WC?	✓		
16	Is the tap appropriate for use by someone with limited dexterity, grip or strength?	✓		
17	Are suitable grab rails fitted in all the appropriate positions to facilitate use of the WC?	✓		
18	Is the manoeuvring area free of obstruction, eg boxed-in pipework/radiators/cleaner's equipment/disposal bins/occasional storage, etc. and is any difficulty caused by the activity of service contractors?	✓		
19	If there is more than one standard layout WC compartment provided, are they handed to offer a left-sided approach and a right-sided approach?	✓		

General Notes for lavatories:

In the disabled toilet in the original building...

- Washing facilities are within reach but not drying facilities
- Pipe work is not boxed in but no hazard caused by this
- Consider better storage of changing equipment

APPENDIX A - 7 of 9

Access Check List for St Agnes Academy– January 2022 <u>Fixtures and Fittings</u>

Consider each question from the perspective of each type of disability:

	Question	Υ	N	Action Point
1	Is any server/counter accessible to all users, including those with hearing impairments?	✓		
2	Is it possible for people with disabilities to serve as volunteers?	\checkmark		
3	Where there are display stands, bookstalls etc. are they visible/reachable/accessible by people with disabilities?	✓		
4	In any eating/meeting space do tables, chairs and the layout allow for use by wheelchair users and other people with disabilities?	✓		
5	In any staff accommodation is it suitable for use by people with disabilities including wheelchair users with slip-resistant floor, reduced level kitchen units and sink and lever action taps?			N/A
6	Are all relevant locations clearly signed?			N/A

General Notes for fixtures and fittings:

Limited room in original building Staff Room, chairs can be removed if required

APPENDIX A - 8 of 9

Access Check List for St Agnes Academy – January 2022 Information

Consider each question from the perspective of each type of disability:

	Question	Υ	N	Action Point
1	Is the building equipped to provide hearing assistance?	✓		Loop system no longer used by hearing support team, radio systems used instead and provided by hearing team as required
2	Does lighting installation of the building take into account the needs of people with visual disabilities?	✓		
3	Are there large-print versions of information about the building/activities available?		✓	
4	Is there braille information available for people with visual disabilities?		✓	

General Notes for information:

Large print versions and Braille versions of information are not available – to be made available on request

APPENDIX A - 9 of 9

Access Check List for St Agnes Academy – January 2022 <u>Means of Escape</u>

Consider each question from the perspective of each type of disability:

	Question	Υ	N	Action Point
1	Is there a visible as well as audible fire alarm system?	\checkmark		
2	Are final exit routes as accessible to all, including wheelchair users, as are the entry routes?	✓		
3	Is there a 'management evacuation strategy' for staff, pupils and visitors, and are staff trained in evacuation procedures?	✓		
4	Is the evacuation strategy checked regularly for its effectiveness?	✓		
5	Are evacuation routes checked routinely and regularly for freedom from combustible materials/obstacles/locked doors?	✓		
6	Are all fire warning devices and detectors checked routinely and regularly	✓		

General Notes for information:		
General Notes for information:		

Appendix B

The accessibility plan shows how access is to be improved for students with disabilities, staff and visitors to the school in a given timeframe and anticipating the need to make reasonable adjustments to accommodate their needs where practicable. Following the audit in Appendix A the key actions are below:-

Term	Target	Strategy	Outcome	Time Frame	Goal Achieved
Long Term	Large print and brail versions of information to be made available if and when necessary.	Ensure tactile information is provided when necessary. Ensure staff know how to access such materials.		As and when require d	
	Signage across the school will be consistent, clear, well positioned and accessible to all.	Consider the position and detail of signage across the school - accurate maps of school buildings and grounds - disabled toilets - wheel chair friendly exits and entrances - additional signage for reception area closer to car park - alternative slopes/ lift at the top and bottom of steps		By 09/202 3	

Summary

St Agnes Academy is an accessible school and site.

Actions flagged are long term targets requiring small amounts of expenditure in the purchase or preparation of fixtures, fittings and signage. These actions could be addressed relatively quickly if required.

Reviewed and updated by Jess Mills September 2022.										
A 3.6	, D1				D 16					